SAFETY DATA SHEET

SealBoss 6060, A-Side OCT 1, 2018

SECTION 1) CHEMICAL PRODUCT AND SUPPLIER'S IDENTIFICATION

Product ID :	SealBoss 6060, A-Side		
Product Name :	SealBoss 6060, A-Side		
Revision Date :	OCT 1, 2018	Date Printed :	OCT 1, 2018
Version:	1.0	Supersedes Date :	N.A.
Suplier Name :	Bayset Pty Ltd		
Address :	P.O. Box 1212, Archerfield BC QLD 4108	3	
Emergency Phone :	Chem Tel International 01-813-248-058	35 Poisons Information Centi	re: 13 11 26
Information Phone :	+61 7 3722 3700		
Fax :	+61 7 3722 3833		
Product/Recommended Uses	: For Further Information, Refer to the Pro	oduct Technical Data Sheet.	

SECTION 2) HAZARDS IDENTIFICATION

Classification:

Specific Target Organ Toxicity -Single Exposure (Respiratory Tract Irritation) - Category 3

Specific Target Organ Toxicity - Repeated Exposure - Category 2

Skin Irritation - Category 2

Respiratory Sensitizer (Solid/Liquid) - Category 1

Skin Sensitizer - Category 1

Carcinogenicity - Category 2

Eye Irritation - Category 2

Acute toxicity, Inhalation - Category 4

Acute toxicity, Oral - Category 5

Pictograms:



Signal Word:

Danger

Hazardous Statements - Health:

H332 - Harmful if inhaled

H303 - Maybe harmful if swallowed

H351 - Suspected of causing cancer.

H319 - Causes serious eye irritation

H334 - May cause allergy or asthma symptoms or breathing difficulties if inhaled

H315 - Causes skin irritation

H317 - May cause an allergic skin reaction

H373 - May cause damage to organs through prolonged or repeated exposure.

H335 - May cause respiratory irritation

Precautionary Statements - General:

P101 - If medical advice is needed, have product container or label at hand.

P102 - Keep out of reach of children.

P103 - Read label before use.

Precautionary Statements - Prevention:

- P261 Avoid breathing dust/fume/gas/mist/vapors/spray.
- P271 Use only outdoors or in a well-ventilated area.
- P201 Obtain special instructions before use.
- P202 Do not handle until all safety precautions have been read and understood.
- P280 Wear protective gloves/protective clothing/eye protection/face protection.
- P264 Wash thoroughly after handling.
- P284 [In case of inadequate ventilation] wear respiratory protection.
- P272 Contaminated work clothing should not be allowed out of the workplace.
- P260 Do not breathe dust/fume/gas/mist/vapors/spray.
- P233 Keep container tightly closed.

Precautionary Statements - Response:

- P304 IF INHALED:
- P340 Remove person to fresh air and keep comfortable for breathing.
- P312 Call a POISON CENTER/doctor if you feel unwell.
- P308 IF exposed or concerned:
- P313 Get medical advice/attention.
- P305 IF IN EYES:
- P351 Rinse cautiously with water for several minutes.
- P338 Remove contact lenses, if present and easy to do. Continue rinsing.
- P337 If eye irritation persists:
- P342 If experiencing respiratory symptoms:
- P311 Call a POISON CENTER/doctor.
- P302 IF ON SKIN:
- P352 Wash with plenty of water.
- P321 Specific treatment (see section 4 on this SDS).
- P332 If skin irritation occurs:
- P362 Take off contaminated clothing.
- P364 And wash it before reuse.
- P333 If skin irritation or a rash occurs:
- P314 Get Medical advice/attention if you feel unwell.

Precautionary Statements - Storage:

P405 - Store locked up.

P403 - Store in a well-ventilated place.

Precautionary Statements - Disposal:

P501 - Dispose of contents/ container to an approved waste disposal plant.

CAS	Chemical Name	% by Weight			
0000101-68-8	4,4'-METHYLENEDIPHENYL DIISOCYANATE	33% - 61%			
0026447-40-5	MDI (MONOMER)	4% - 8%			

SECTION 4) FIRST-AID MEASURES

Inhalation:

Remove source of exposure or move person to fresh air and keep comfortable for breathing. If experiencing respiratory symptoms: Call a POISON CENTER/doctor. If breathing is difficult, trained personnel should administer emergency oxygen if advised to do so by the POISON CENTER/doctor.

If exposed/feel unwell/concerned: Call a POISON CENTER/doctor.

Eliminate all ignition sources if safe to do so.

Skin Contact:

Take off contaminated clothing, shoes and leather goods (e.g. watchbands, belts). Gently blot or brush away excess product. Wash with plenty of lukewarm, gently flowing water for a duration of 15-20 minutes. If skin irritation or rash occurs: Get medical advice/attention. Wash contaminated clothing before re-use or discard.

IF exposed or concerned: Get medical advice/attention.

Eye Contact:

Avoid direct contact. Wear chemical protective gloves, if necessary.

Rinse eyes cautiously with lukewarm, gently flowing water for several minutes, while holding the eyelids open. Remove contact lenses, if present and easy to do. Continue rinsing for 15-20 minutes. Take care not to rinse contaminated water into the unaffected eye or onto the face. If eye irritation persists: Get medical advice/attention.

Ingestion:

Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER/doctor. If vomiting occurs naturally, lie on your side, in the recovery position.

IF exposed or concerned: Get medical advice/attention.

SECTION 5) FIRE-FIGHTING MEASURES

Suitable Extinguishing Media:

Dry chemical, foam, carbon dioxide is recommended. Water spray is recommended to cool or protect exposed materials or structures. Carbon dioxide can displace oxygen. Use caution when applying carbon dioxide in confined spaces. Simultaneous use of foam and water on the same surface is to be avoided as water destroys the foam. Sand or earth may be used for small fires only.

Unsuitable Extinguishing Media:

If water is used, use very large quantities of cold water. The reaction between water and hot isocyanate may be vigorous.

Specific Hazards in Case of Fire:

Vapors may accumulate and travel to ignition sources distant from the handling site; flash fire can occur.

Excessive pressure or temperature may cause explosive rupture of containers.

Water contamination will produce carbon dioxide. Do not reseal contaminated containers as pressure buildup may rupture them.

Fire-fighting Procedures:

Isolate immediate hazard area and keep unauthorized personnel out. Stop spill/release if it can be done safely. Move undamaged containers from immediate hazard area if it can be done safely. Water spray may be useful in minimizing or dispersing vapors and to protect personnel. Water may be ineffective but can be used to cool containers exposed to heat or flame. Caution should be exercised when using water or foam as frothing may occur, especially if sprayed into containers of hot, burning liquid.

Dispose of fire debris and contaminated extinguishing water in accordance with official regulations.

Special Protective Actions:

Wear NIOSH approved self-contained breathing apparatus in positive pressure mode with full-face piece. Boots, gloves (neoprene), googles, and full protective clothing are also required.

Care should always be exercised in dust/mist areas.

SECTION 6) ACCIDENTAL RELEASE MEASURES

Emergency Procedure:

ELIMINATE all ignition sources (no smoking, flares, sparks or flames in immediate area).

Do not touch or walk through spilled material.

Isolate hazard area and keep unnecessary people away. Remove all possible sources of ignition in the surrounding area. Notify authorities if any exposure to the general public or the environment occurs or is likely to occur.

If spilled material is cleaned up using a regulated solvent, the resulting waste mixture may be regulated.

Recommended Equipment:

Positive pressure, full-face piece self-contained breathing apparatus(SCBA), or positive pressure supplied air respirator with escape SCBA (NIOSH approved).

Personal Precautions:

Avoid breathing vapors. Avoid contact with skin, eyes or clothing. Do not touch damaged containers or spilled materials unless wearing appropriate protective clothing.

Environmental Precautions:

Stop spill/release if it can be done safely. Prevent spilled material from entering sewers, storm drains, other unauthorized drainage systems and natural waterways by using sand, earth, or other appropriate barriers.

Methods and Materials for Containment and Cleaning up:

Cover container, but do not seal, and remove from work area. Prepare a decontamination solution of 2.0% liquid detergent and 3-8% concentrated ammonium hydroxide in water (5-10% sodium carbonate may be substituted for the ammonium hydroxide). Follow the precautions on the supplier's safety data sheets.

Treat the spill area with the decontamination solution, using about 10 parts of the solution for each part of the spill, and allow it to react for at least 15 minutes. Carbon dioxide will be evolved, leaving insoluble polyureas. Residues from spill cleanup, even when treated as described may continue to be regulated under provisions of RCRA and require storage and disposal as hazardous waste.

Slowly stir the isocyanate waste into the decontamination solution described above. Let stand for 48 hours, allowing the evolved carbon dioxide to vent away, residues may still be subject to RCRA storage and disposal requirements. Dispose off in compliance with all relevant local, state, and federal laws and regulations regarding treatment.

SECTION 7) HANDLING AND STORAGE

General:

Wash hands after use. Do not get in eyes, on skin or on clothing. Do not breathe vapors or mists. Use good personal hygiene practices. Eating, drinking and smoking in work areas is prohibited. Remove contaminated clothing and protective equipment before entering eating areas.

Ventilation Requirements:

Use only with adequate ventilation to control air contaminants to their exposure limits. The use of local ventilation is recommended to control emissions near the source.

Storage Room Requirements:

Keep container(s) tightly closed and properly labeled. Store in cool, dry, well-ventilated areas away from heat, direct sunlight, strong oxidizers and any incompatibilities. Store in approved containers and protect against physical damage. Keep containers securely sealed when not in use. Indoor storage should meet OSHA standards and appropriate fire codes. Containers that have been opened must be carefully resealed to prevent leakage. Empty container retain residue and may be dangerous. Use non-sparking ventilation systems, approved explosion-proof equipment and intrinsically safe electrical systems in areas where this product is used and stored.

Ground and bond containers and receiving equipment. Avoid static electricity by grounding.

Do not cut, drill, grind, weld, or perform similar operations on or near containers. Do not pressurize containers to empty them. Ground all structures, transfer containers and equipment to conform to the national electrical code. Use procedures that prevent static electrical sparks. Static electricity may accumulate and create a fire hazard.

SECTION 8) EXPOSURE CONTROLS/PERSONAL PROTECTION

Eye Protection:

Wear eye protection with side shields or goggles. Wear indirect-vent, impact and splash resistant goggles when working with liquids. If additional protection is needed for entire face, use in combination with a face shield.

Skin Protection:

Use of gloves approved to relevant standards made from the following materials may provide suitable chemical protection: PVC, neoprene or nitrile rubber gloves. Suitability and durability of a glove is dependent on usage, e.g. frequency and duration of contact, chemical resistance of glove material, glove thickness, dexterity. Always seek advice from glove suppliers. Contaminated gloves should be replaced. Use of an apron and over- boots of chemically impervious materials such as neoprene or nitrile rubber is recommended to avoid skin sensitization. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. Launder soiled clothes or properly disposed of contaminated material, which cannot be decontaminated.

Depending on conditions of use, additional protection may be required such as apron, arm covers, or full body suit. Wash contaminated clothing before re-wearing.

Respiratory Protection:

If airborne concentrations exceed or are expected to exceed the TLV, use MSHA/NIOSH approved positive pressure supplied pressure supplied air respiratory with a full face piece or an air supplied hood. For emergencies, use a positive pressure self-contained breathing apparatus. Air purifying (cartridge type) respirators are not approved for protection against isocyanates.

Appropriate Engineering Controls:

Provide exhaust ventilation or other engineering controls to keep the airborne concentrations of vapors below their respective threshold limit value.

Chemical Name	OSHA TWA	OSHA TWA	OSHA STEL	OSHA STEL	OSHA- Tables-	OSHA	OSHA Skin	NIOSH TWA	NIOSH TWA	NIOSH STEL	NIOSH STEL	NIOSH
	(ppm)	(mg/m3)	(ppm)	(mg/m3)	Z1,2,3	Carcinogen	designation	(ppm)	(mg/m3)	(ppm)	(mg/m3)	Carcinogen

4,4'- METHYLENEDIPHEN	0.02	0.2 ceiling	1		0.005	0.050		
YL DIISOCYANATE	ceiling							

Chemical Name	ACGIH	ACGIH	ACGIH	ACGIH
	TWA	TWA	STEL	STEL
	(ppm)	(mg/m3)	(ppm)	(mg/m3)
4,4'- METHYLENEDIPHEN YL DIISOCYANATE	0.005	0.051		

SECTION 9) PHYSICAL AND CHEMICAL PROPERTIES

Physical and Chemical Properties

Density 9.52 lb/gal Specific Gravity 1.14 VOC Regulatory 0.00 lb/gal VOC Part A & B Combined N.A. Appearance Clear Liquid Odor Threshold N.A. Odor Description Mild Aromatic pH N.A. Water Solubility Reacts with Water Flash Point Symbol N.A. Flash Point Symbol N.A. Lower Explosion Level N.A. Vapor Pressure N.A. Vapor Density Heavier than air Freezing Point N.A. Metting Point N.A. Auto Ignition Temp N.A. Decomposition Pt N.A. Evaporation Rafe Slower than ether Coefficient Water/Oil N.A.	1					
VOC Regulatory0.00 lb/galVOC Part A & B CombinedN.A.AppearanceClear LiquidOdor ThresholdN.A.Odor DescriptionMild AromaticpHN.A.Water SolubilityReacts with WaterFlammabilityN/A.Flash Point SymbolN.A.Flash Point SymbolN.A.Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Lower Bining PointN.A.Vapor DensityHeavier than airFreezing PointN.A.Lower Bining	Density	9.52 lb/gal				
VOC Part A & B CombinedN.A.AppearanceClear LiquidOdor ThresholdN.A.Odor DescriptionMild AromaticpHN.A.Water SolubilityReacts with WaterFlammabilityN/AFlash Point SymbolN.A.Flash Point200 °FViscosityN.A.Lower Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Lowe Boiling PointN.A.Lower Explosion LevelN.A.Vapor DensityHeavier than airFreezing PointN.A.Lower Boiling PointN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Specific Gravity	1.14				
AppearanceClear LiquidOdor ThresholdN.A.Odor DescriptionMild AromaticpHN.A.Water SolubilityReacts with WaterFlammabilityN/AFlash Point SymbolN.A.ViscosityN.A.Lower Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Metting Point302 °FHigh Boiling PointN.A.Low Boiling PointN.A.Low Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	VOC Regulatory	0.00 lb/gal				
Odor ThresholdN.A.Odor DescriptionMild AromaticpHN.A.Water SolubilityReacts with WaterFlammabilityN/AFlash Point SymbolN.A.Flash Point SymbolN.A.Flash Point SymbolN.A.ViscosityN.A.Lower Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Metting PointS02 °FHigh Boiling PointN.A.Lower Explosion LevelN.A.Vapor DensityHeavier than airFreezing PointN.A.Auto Ignition TempN.A.Auto Ignition TempN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	VOC Part A & B Combined	N.A.				
Odor DescriptionMild AromaticpHN.A.Water SolubilityReacts with WaterFlammabilityN/AFlash Point SymbolN.A.Flash Point Symbol200 °FViscosityN.A.Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Metting Point00 °FLow Boiling PointN.A.Low Boiling PointN.A.Low Boiling PointN.A.Auto Ignition TempN.A.Pecomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Appearance	Clear Liquid				
HN.A.Water SolubilityReacts with WaterFlammabilityN/AFlash Point SymbolN.A.Flash Point200 °FViscosityN.A.Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Lowe Biling PointN.A.Vapor DensitySolution CompositionPointN.A.Lowe Biling PointN.A.Lowe Biling PointN.A.Lowe Biling PointN.A.Vator InterpoN.A.Vator InterpoN.A.Lowe Biling PointN.A.Auto Ignition TempN.A.Vapor DensitySower than etherCoefficient Water/OilN.A.	Odor Threshold	N.A.				
Water SolubilityReacts with WaterFlammabilityN/AFlash Point SymbolN.A.Flash Point200 °FViscosityN.A.Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Metting Point302 °FHigh Boiling PointN.A.Lower Explosion LevelN.A.Vapor DensityHeavier than airFreezing PointN.A.Auto Ignition TempN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Odor Description	Mild Aromatic				
FlammabilityN/AFlash Point SymbolN.A.Flash Point200 °FViscosityN.A.Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Melting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	рН	N.A.				
Flash PointN.A.Flash Point200 °FViscosityN.A.Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Metting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Water Solubility	Reacts with Water				
Flash Point200 °FViscosityN.A.Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Metting PointN.A.Low Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Flammability	N/A				
ViscosityN.A.Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Melting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Flash Point Symbol	N.A.				
Lower Explosion LevelN.A.Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Melting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Flash Point	200 °F				
Upper Explosion LevelN.A.Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Melting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Viscosity	N.A.				
Vapor PressureN.A.Vapor DensityHeavier than airFreezing PointN.A.Melting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Lower Explosion Level	N.A.				
Vapor DensityHeavier than airVapor DensityN.A.Freezing PointN.A.Melting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Upper Explosion Level	N.A.				
Freezing PointN.A.Melting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Vapor Pressure	N.A.				
Melting PointN.A.Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Vapor Density	Heavier than air				
Low Boiling Point302 °FHigh Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Freezing Point	N.A.				
High Boiling PointN.A.Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Melting Point	N.A.				
Auto Ignition TempN.A.Decomposition PtN.A.Evaporation RateSlower than etherCoefficient Water/OilN.A.	Low Boiling Point	302 °F				
Decomposition Pt N.A. Evaporation Rate Slower than ether Coefficient Water/Oil N.A.	High Boiling Point	N.A.				
Evaporation RateSlower than etherCoefficient Water/OilN.A.	Auto Ignition Temp	N.A.				
Coefficient Water/Oil N.A.	Decomposition Pt	N.A.				
	Evaporation Rate	Slower than ether				
	Coefficient Water/Oil	N.A.				

SECTION 10) STABILITY AND REACTIVITY

Stability:

Material is stable at standard temperature and pressure.

Conditions to Avoid:

Heat, high temperature, open flame, sparks, and moisture. Contact with incompatible materials in a closed system will cause liberation of carbon dioxide and buildup of pressure.

Hazardous Reactions/Polymerization:

Will not occur under normal conditions but under high temperatures in the presence of alkalis, tertiary amines, and metal compounds will accelerate polymerization. Possible evolution of carbon dioxide gas may rupture closed containers.

Incompatible Materials:

This product will react with any material containing active hydrogens, such as water, alcohol, ammonia, amines, alkalis and acids, the reaction with water is slow under 50°C, but is accelerated at higher temperature and in the presence of alkalis, tertiary amines, and metal compounds. Some reactions can be violent. Material can react with strong oxidizing agents.

Hazardous Decomposition Products:

SECTION 11) TOXICOLOGICAL INFORMATION

Skin Corrosion/Irritation:

Isocyanates react with skin protein and moisture and can cause irritation. Prolonged contact can cause reddening, swelling, rash, scaling, blistering, and, in some cases, skin sensitization. Individuals who have developed a skin sensitization can develop these symptoms as a result of contact with very small amounts of liquid material or as a result of exposure to vapor. Causes skin irritation

Causes skill initiation

Serious Eye Damage/Irritation:

Liquid, aerosols or vapors are severely irritating and can cause pain, tearing, reddening and swelling. Prolonged vapor contact may cause conjunctivitis. Any level of contact should not be left untreated.

Causes serious eye irritation

Carcinogenicity:

Suspected of causing cancer.

Respiratory/Skin Sensitization:

May cause allergy or asthma symptoms or breathing difficulties if inhaled

May cause an allergic skin reaction

Germ Cell Mutagenicity:

No data available

Reproductive Toxicity:

No data available

Specific Target Organ Toxicity - Single Exposure:

May cause respiratory irritation

Specific Target Organ Toxicity - Repeated Exposure:

May cause damage to organs through prolonged or repeated exposure.

Aspiration Hazard:

No data available

Acute Toxicity:

No data available

0000101-68-8 4,4'-METHYLENEDIPHENYL DIISOCYANATE

LC50 (rat): 369-490 mg/m3 (aerosol) (4-hour exposure) (1) LC50 (rat): 178 mg/m3 (17.4 ppm) (duration of exposure not reported) (2)

LD50 (oral, rat): greater than 10,000 mg/kg (1,2) LD50 (dermal, rabbit): greater than 10,000 mg/kg (1) LD50 (oral, mouse): 2,200 mg/kg (3)

SECTION 12) ECOLOGICAL INFORMATION

Toxicity:

No data available.

Persistence and Degradability:

No data available.

Bioaccumulative Potential:

No data available.

Mobility in Soil:

No data available.

Other Adverse Effects:

No data available.

Waste Disposal:

Under RCRA, it is the responsibility of the user of the product, to determine a the time of disposal whether the product meets RCRA criteria for hazardous waste. Waste management should be in full compliance with federal, state, and local laws.

Empty containers retain product residue which may exhibit hazards of material, therefore do not pressurize, cut, glaze, weld or use for any other purposes. Return drums to reclamation centers for proper cleaning and reuse.

SECTION 14) TRANSPORT INFORMATION

U.S. DOT Information:

Not regulated

IMDG Information:

Not regulated.

IATA Information:

Not regulated.

SECTION 15) REGULATORY INFORMATION

CAS	Chemical Name	% By Weight	Regulation List
0000101-68-8	4,4'- METHYLENEDIPHENYL DIISOCYANATE	33% - 61%	CERCLA, HAPS, SARA312, SARA313, VHAPS, VOC, TSCA
0026447-40-5	MDI (MONOMER)	4% - 8%	SARA312,TSCA

SECTION 16) OTHER INFORMATION

OTHER INFORMATION:

Note: As per GHS, category 1 is the greatest level of hazard within each class.

GLOSSARY:

ACGIH- American Conference of Governmental Industrial Hygienists; ANSI- American National Standards Institute; Canadian TDG-Canadian Transportation of Dangerous Goods; CAS- Chemical Abstract Service; Chemtrec- Chemical Transportation Emergency Center (US); CHIP- Chemical Hazard Information and Packaging; DSL- Domestic Substances List; EC- Equivalent Concentration; EH40 (UK)-HSE Guidance Note EH40 Occupational Exposure Limits; EPCRA- Emergency Planning and Community Right-To-Know Act; ESL- Effects screening levels; HMIS- Hazardous Material Information Service; LC- Lethal Concentration; LD- Lethal Dose; NFPA- National Fire Protection Association; OEL- Occupational Exposure Limits; OSHA- Occupational Safety and Health Administration, US Department of Labor; PEL- Permissible Exposure Limit; SARA (Title III)- Superfund Amendments and Reauthorization Act; SARA 313- Superfund Amendments and Reauthorization Act, Section 313; SCBA- Self-Contained Breathing Apparatus; STEL- Short Term Exposure Limit; TCEQ - Texas Commission on Environmental Quality; TLV- Threshold Limit Value; TSCA- Toxic Substances Control Act Public Law 94-469; TWA

- Time Weighted Value; US DOT- US Department of Transportation; WHMIS- Workplace Hazardous Materials Information System.

DISCLAIMER

Limited Warranty Policy and Disclaimer for Products Supplied and/or Distributed by SealBoss Corp.: All recommendations, statements and technical data herein are based on tests we believe to be reliable and correct, but accuracy and completeness of said tests are not guaranteed and are not to be construed as a warranty either expressed or implied. User shall rely on his or her own information and tests to determine suitability of the product for the intended use and user assumes all risk and liability resulting from his or her use of the product. Nothing contained in any supplied materials relieves the user of the obligation to read and follow the warnings and instruction for each product as set forth in the current Technical Data Sheet, product label and Material Safety Data Sheet prior to product use. SealBoss Corp. warrants supplied / distributed products to be free of manufacturing defects. Seller's and manufacturer's sole responsibility shall be to replace that portion of the product of the manufacturer which proves to be defective. There are no other warranties by SealBoss Corp. of any nature whatsoever expressed or implied, including any warranty of merchantability or fitness for a particular purpose in connection with this product. SealBoss Corp. shall not be liable for damages of any sort, including remote or consequential damages resulting from any claimed breach of any warranty whether expressed or implied. SealBoss Corp. shall not be responsible for use of this product in a manner to infringe on any patent or any other intellectual property rights held by others. In addition, no warranty or guarantee is being issued with respect to appearance, color, fading, chalking, staining, shrinkage, peeling, UV damage, excessive temperature exposure, normal wear and tear or improper application by the applicator. Damage caused by abuse, neglect and lack of proper maintenance, acts of nature and / or physical movement of the substrate or structural defects are also excluded from the limited warranty. SealBoss Corp. reserves the right to conduct performance tests on any material claimed to be defective prior to any repairs by owner, general contractor, or applicator. Neither seller nor manufacturer shall be liable to the buyer or any third person for any injury, loss or damage directly or indirectly resulting from use of or inability to use the product. Recommendations and statements other than those contained in a written agreement signed by an officer of the manufacturer shall not be binding upon the manufacturer or seller. SealBoss Corp. reserves the right to change the properties of products without notice.